2 9 AUG 1974

MEMORANDUM FOR: Director of Logistics

THROUGH : Chief, Real Estate and Construction Division, OL

SUBJECT : Funds for New Air Handlers

REFERENCE: Computer Systems Planning Report dtd 6 Jun 74

by OJCS

1. A request for guidance in the funding of \$14,000 for the procurement and installation of new air handlers in room GC03, Office of Joint Computer Support (OJCS), is requested in paragraph 6.

- 2. The referent report identified a matrix of generalized space and utility requirements against various computer configuration assumptions through FY 1978. Specific equipment locations were not included in the report.
- 3. The specific equipment location for Milestone No. 1 of the report, the installation of the IBM 370/158-2, has now been identified. The unit is scheduled to be located in the southwest quadrant of GC03 served by perimeter air handler Nos. 6 and 7.
- 4. As previously identified, the underfloor congestion and multiple heating, ventilating, and air conditioning (HVAC) systems serving the GCO3 area present indeterminacy in HVAC designs. Within the constraints of this indeterminacy, analysis indicates that the existing air handlers may not have the capacity to meet the increased requirements of the 370/158-2 installation. In lieu of an indepth engineering study and relatively extensive modifications in the instrumentations and control of the HVAC systems, the only sure alternative to insure an acceptable environment will exist to support the installation in the area is to uprate air handler Nos. 6 and 7 from a 10-ton rating to a 20-ton rating. This will be an ad hoc action to insure adequate results for a specific installation in a specific area. This action will not contribute to the resolution of the overall HVAC problems in the OJCS Computer Center, nor will it necessarily be effective if the location of the 370/158-2 is altered to a new location in a different quadrant of the Center.

5.	OJCS	representatives	are	in	agreement	that	upra	ted	air	
		necessary, but				advis	es t	hat	ojcs	STAT

Approved For Release 2003/06/20 : CIA-RDP86-01019R000100240007-2

SUBJECT: Funds for New Air Handlers

FY 1975 funds are not available for this unanticipated requirement. The budgetary cost estimate for procurement and installation of the uprated units is \$14,000.

There is mutual agreement between Real Estate and Construction Division and OJCS that air handler Nos. 6 and 7 must be uprated to insure that an adequate environment will exist to support the new 370/158-2 computer. Neither OJCS nor OL has programmed funds in FY 1975 for this unanticipated requirement. OJCS has advised that funds are not available, and has requested OL to identify funds. Guidance is requested in the identification of approximately \$14,000 for the uprating of air handler Nos. 6 and 7.

STAT

Headquarters Engineering Branch, RECD/OL

		ROUTIN	G AND	RECOR	D SHEET		
SUBJECT	: (Optional)				· · · · · · · · · · · · · · · · · · ·		
	Funds for New Air	Hand1e:	rs				
FROM:				EXTENSION	NO.		
	C/HEB/RECD/OL 2F42 Hqs.				DATE ST		
					31		
TO: (Off building)	ficer designation, room number, and	DATE		OFFICER'S	COMMENTS (Number each comment to show from whom		
		RECEIVED	FORWARDED	INITIALS	to whom. Draw a line across column after each comment.)		
1.	C/RECD/OL		0 NUC 46	74	D		
	906 Ames	2	9 AUG 19	7007	RE: Paragraph 6		
2.				9 ~~~	Glenn:		
				!	Assume RECD would recommend		
3.					OL funds under policy that		
					planning and control of utilit		
4.			-		systems may be achieved only if RECD is the sole source of		
					funding utility-related pro-		
5.	The state of the s				Jects. Possible we should		
J.					include a relatively large but undefined line item in FY 76		
					for unanticipated projects		
6.					like this and the GJ56 9K $_{ m ex}$ -		
					penditure. As I see it, there are four alternatives as		
7.					follows listed in order of my		
					perception of desirability:		
8.	· · · · · · · · · · · · · · · · · · ·				a. OL fund out of 1121		
				:	funds		
9.					b. OL reprogram and		
					fund		
10.			1	-	c. OL advise OJCS to		
					reprogram through DD		
1.							
					d. Chance it and try to get adequate air int		
					the location from		
2.					spare capacity in		
					other air handlers.		
13.					To meet the Oct. installation		
					date, procurement must be ST initiated in the immediate		
14.					future. This memo has been		
		-			coordinated with		
5.					of OJCS.		
	Approved For Poloce	2002/0	 6/20 : CIA	DDD96	1019R00010024000712		

Next 3 Page(s) In Document Exempt